

EETD Near Hits - Representative Sampling							Updated: 10/22/2008
Date	Location	PI	Work Lead	Facility No.	Dept.	Description (No injuries except where noted)	Corrective Action
8/31/2004	70	Various	Various	n/a	n/a	Numerous water leaks (the last being on this date) creating slip and electrical hazards.	Repaired. EETD conducted extent of condition review. Further corrective actions pending.
8/31/2004	70-269	Ted Chang	Ted Chang	6	AET	Lab users w/o PPE. (Date approx.)	Users told to use appropriate PPE.
8/31/2004	70-269	Gao Liu	Gao Liu	37	BT	Lab user w/o PPE. (Date approx.)	User told to use appropriate PPE.
12/11/2003	Cyclotron Rd.	Steve Chu Brett Singer		35	AS	Bike vs. pedestrian accident caused moderate injury.	Evaluate hazard lab-wide. Publicity campaign. Improved parking crossing markings and signage.
6/20/2003	Field	Melissa Lunden	Melissa Lunden	35	AS	Electric shock from faulty ground.	Equipment and house wiring reviewed and repaired by qualified electricians.
11/15/2002	90 Exterior	Unknown	Unknown	n/a	n/a	Bike rider on ramp and deck slipped and fell.	Building-wide notices sent - no bike riding on decks or ramps. Signs posted.
9/26/2001	70-173	R. Cheng D. Littlejohn	Dave Littlejohn	7	AET	Plumber walked into laser lab without PPE, with laser running.	Procedures review and Lab Lessons Learned.
5/17/2001	90 Exterior	N/A	N/A	n/a	Lab	Exterior steel boiler flue pipe badly corroded with potential for collapse.	Replaced by contractor.
5/16/2001	90 Exterior	N/A	N/A	n/a	Lab	Loose steel anti-slip strip sticking up from stair tread, creating trip hazard on steps.	Repaired by Facilities.
5/12/2001	70-215	Tom Kirchstetter	Tom Kirchstetter	21	AS	Unprotected 120 vac terminals.	Repaired.
5/12/2001	70-289	Randy Maddalena	Doug Sullivan	14	IE	Electrical short in a wall-mounted plugstrip outlet.	Plug strip replaced by Facilities.
5/10/2001	62-220	John Kerr	John Kerr	5b	AET	Unprotected 120 vac terminals.	Repaired.
5/8/1999	46-232B	Francis Rubinstein	Dennis DiBartolomeo	24	BT	Flue pipe loose from furnace. Potential for Carbon Monoxide poisoning.	Repaired by Facilities.
1/12/1982	67B-101	Joe Klems	Guy Kelley	16	BT	Lab worker exercised Stop Work authority when poorly designed water tanks nearly failed.	Engineering review conducted and tanks replaced with properly designed vessels.
Approx. 4 per year	EETD	Various		n/a	n/a	Ergonomic Injuries. Early intervention vital to prevent more serious injuries.	Improved ergo training and follow-up, education about early reporting.
Acronyms:							
AHD	Activity Hazard Document (Used to analyze hazards and controls for medium and high hazard operations.)						
JHA	Job Hazards Analysis						
ORPS	Occurrence Reporting and Processing System (DOE incident database)						
PPE	Personal Protective Equipment (safety glasses, gloves, lab coats, etc.)						